



Eagle Technology, Land Information New Zealand, GEBCO, Community maps contributors





**Site Appraisal Photograph 1:** Photograph taken from existing northeast operations yard, looking towards proposed organics processing bunkers, in a southwesterly direction.



**Site Appraisal Photograph 2:** Photograph taken to the east of the landfill on maintenance access track between the Kaikorai River (to the left) and the landfill (to the right).