

HOLE No. :
CO ORDINATES :
LOCATION :
LOCATION

GW19
E 69 249.73
MTG

N 16113.28

JOB NO.
RL

221-60
361.64

drilling method	penetration	water	graphic log	scale (m)	Geological Log	Borehole Construction Details	bailing yield and additional observations
REVERSE CIRCULATION				0	Brown strongly oxidised semi psammitic schist	Cap	
				1		Cement grout	
				2			
				3			
				4	Lt brown moderately oxidised semi psammitic schist		50mm Ø PVC pipe
				5			
				6	Lt grey fresh semi psammitic schist		
				7			
				8		Bentonite	Backfill
				9			
				10		Gravel	
				11			140mm Ø hole
				12			
				13			50mm Ø PVC screen
				14			
				15			End Cap
				16			
				17			
				18			
				19			
				20			
				21			
				22			
				23			
				24			
				25			
				26			
				27			
			28				

DRILL TYPE : SCHRAMM
FEED :
DRILLER : HOODS
COMMENCED : 29-6-92
COMPLETED :
LOGGED BY : TRF
CHECKED BY :
VERTICAL SCALE :

KEY
penetration
no resistance ranging to refusal

water
10.01.80 water level and date
water inflow
water outflow

CLIENT
MACRAES MINING COMPANY LIMITED

PROJECT :
MACRAES EXTENDED PROJECT

GROUNDWATER INVESTIGATION
LOG OF BORE

Woodward-Clyde



DATE :
JULY 1992

DRAWING NO

FIGURE NO